

# Scan Results – Vancouver 2016

<u>DTC</u>	<u>OE</u>	<u>OE ASSISTED</u>	<u>AFTERMARKET</u>
<b>ENGINE AND ECT</b>			
P0335	x	x	x
P1304	x	x	
P1603	x	x	x
P1604	x	x	x
P1605	x	x	x
<b>FOUR WHEEL DRIVE</b>			
C1280	x		x
C1337	x	x	x
<b>AIR CONDITONER</b>			
B1423	x	x	x
<b>SRS AIRBAG</b>			
B1801	x	x	x
B1802	x	x	x
B1803	x	x	x
B1806	x	x	x
B1807	x	x	x
B1811	x	x	x
B1813	x	x	x
B1816	x	x	x
B1831	x		x
B1836	x	x	x
B1861	x	x	x
B1901	x	x	x
B1906	x	x	x
B1941	x	x	x
<b>BLIND SPOT MONIOTR MASTER</b>			
C1AB4	x	x	
<b>MAIN BODY</b>			
U0100	x	x	x
U0101	x	x	x
U0151	x	x	x
U0201	x	x	x
U0202	x	x	x
<b>ABS/VSC/TRAC</b>			
C1441	x	x	x
<b>AIR CONDITIONER</b>			
B1423	x	x	x
<b>DRIVER DOOR MOTOR</b>			
B2312	x	x	x
<b>SMART KEY</b>			
U0142	x	x	x
U0155	x	x	x
<b>PASSENGER DOOR MOTOR</b>			
B2312	x	x	x